## Comments Ironmaking

## Material Handling

- The Plan should include contingencies should fugitive emissions be found beyond the fence line. Sporadic visual inspections may not be adequate to determine ongoing compliance.

## Sinter Plant

2	Cold Screening (BFSPCS-F) with Baghouse (BFSPCHSB-S)  Cooler (BFSPCO-F) with Multicyclone (BFSPCOM-S) Discharge End Fugitives (BFSPSSDE-F) Hot Screening (BFSPHS-F) with Baghouse (BFSPCHSB-S) Sinter Strand with Windbox Cyclones (BFSPC-F) Sinter Strand with Scrubber No 1 (BFSPFC1S-S) Sinter Strand with Scrubber No. 2 (BFSPFC2S-S) Sinter Strand Roof Monitor (BFSPSSRM-F) Water Treatment Lime Silo with Baghouse (BFSPWTLSB-S)	
_		